



DATUM / DATE : 21.08.2012

SUBJECT: EXTENDING OF THE SERVICE INTERVAL / PRODLOUŽENÍ SERVISNÍHO INTERVALU

PROPELLER MODEL AFFECTED: KLASSIC, WINGLET, SPEEDY, EFFIC AND PROPULS PROPELLERS /
PLATÍ PRO VRTULE KLASSIC, WINGLET, SPEEDY, EFFIC A PROPULS

SERIAL NUMBERS AFFECTED: ALL / VŠECHNA SERIOVÁ ČÍSLA

SERVICE MANUAL AFFECTED: Manual of checking the propellers of type family Klassic, Winglet, Effic, Propuls – REV.A – issued 15.10.2010
The new Manual is REV.B – issued 21.8.2012

Na základě dlouholetých zkušeností z provozu vrtulí typ Klassic, Winglet, Speedy, Propuls a Effic firma WOODCOMP prodlužuje servisní interval vrtulí ze 150 hodin na 500 provozních hodin nebo 2 roky, podle toho co uplyne dříve.

Based on long-term experience with operation of Klassic, Winglet, Speedy, Propuls and Effic propellers, WOODCOMP is hereby extending the service interval of these propellers from 150 to 500 operating hours or 2 years, depending what occurs first.

Manager Accountable Name: Aleš Křemen Sign: 	Date: 21.08.2012
---	---------------------

New edition